



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program January 29, 2013

Reviewed: 

Mine Name: Wolf Creek Mine	Permit Number: S/013/0016
Operator Name: Leon & Sons Excavating LLC	Inspection Date: 09/20/2011
Inspector(s): L Heppler	Time: 3:00 PM
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 03-31-2015 **Bond Amount:** \$7,600 **Annual Permit fee** is upto date

Purpose of Inspection: Routine annual inspection. This site was inspected as a small mine site on 08/25/2010

Inspection Summary: Operator has removed most of the rip rap material stockpiles, since the last inspection in August 2010. No trash was noted on site. No erosion problems were noted on site. Two roads access the working face. Every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

Conclusions and Recommendations: It is the recommendation of the Division that the Operator to implement an interim seeding program of intermediate wheatgrass and smooth brome, so noxious weeds such as Canada and musk thistle will not dominate the site; it would also aid with dust suppression. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:eb

cc: Leon Casper

O:\M013-Duchesne\S0130016-WolfCreek\inspections\Insp-09102011.doc





Cut looking to the east



Mine site – looking to the west



Lower access road – note weeds



Upper access roads – note weeds